



SERVICE PROVIDER

Clearflow Hood Cleaning

Tampa, FL

(555) 010-0142

CUSTOMER

Bayshore Grill

Attn: Tony Sample

3201 Bayshore Blvd, Tampa, FL 33629

DATE

Oct 7, 2026

TIME ON SITE

08:40 – 10:15

TECHNICIAN

Max Doe

CLEANING FREQUENCY

Quarterly

COOKING TYPE

☐ Solid fuel ☐ Wok ☒ Charbroil ☒ Fryers ☐ Other

SYSTEM COMPONENTS

#	ITEM	FINDING	RESULT
01	Hood interior		Cleaned
02	Grease filters		Cleaned
03	Plenum		Cleaned
04	Horizontal duct		Cleaned
05	Vertical duct	No access panel above 2nd floor.	Not cleaned
06	Exhaust fan		Cleaned
07	Grease cups / containment		Cleaned

AREAS NOT CLEANED AND WHY

Vertical duct above the 2nd floor: no access panel.

GREASE DEPTH BEFORE, HOOD/DUCT

0.06 in.

GREASE DEPTH BEFORE, FAN

0.1 in.

SYSTEM CHECKS

#	ITEM	FINDING	RESULT
01	Exhaust fan operates		Pass
02	Belts and pulleys		Pass
03	Fan hinge kit	No hinge kit on upblast fan.	Action needed
04	Filters in place		Pass

#	ITEM	FINDING	RESULT
05	Access panel signage		Pass
06	System diagram posted		Not checked

ACCESS PANELS ADEQUATE

No — panels needed

DEFICIENCIES FOUND


Vertical duct above 2nd floor has no access panel; cannot be cleaned to bare metal.

☒ Certificate / service sticker placed at the hood

NEXT CLEANING DUE
Jan 5, 2027


TECHNICIAN CERTIFICATION #
IKECA CECS 1234

PHOTOS



Plenum before

08:52



Plenum after

09:21



Fan blades after

09:40

CERTIFICATE OF PERFORMANCE

The kitchen exhaust system at this address was cleaned and inspected on the date of this report by the company and technician named here. Areas that were not cleaned are listed above.

TECHNICIAN

Max Doe · 10:22 AM
Certified Exhaust Hood Cleaning Specialist

CUSTOMER

Tony Sample · 10:24 AM